I hereby certify to the parties named above that the real estate described herein was inspected under my supervision on the date indicated and that to the best of my knowledge, this report conforms with the requirements contained in Sections 27 through 29 of 865 IAC 1-1-12 for a SURVEYOR LOCATION REPORT. Unless otherwise noted there is no visible evidence of possession lines found. Legend Note: Fence locations shown are approximate. An accurate Building Line B.L. D.& U.E. Drainage & Utility Easement boundary survey is required Beacon Way - x - Fence ± to determine exact locations. (26.2' Pavement) (50' R/W per Plat) 100.00 20.5 Concrete Drive 31'± 30' D.& U.E. 30' B.L  $\dot{}$ 90'9" Brandon & Madison McCall Concrete-Scale: 1"=30' (317) 697-2864 1419 Beacon Way 10 Carmel, IN 46032 18x36 Tapered - 6' Depth Bmrk - Existing Patio Existing Patio 5 Deck Drain - TBD Sump Pit & Perimeter Drain All Dirt Hauls except for grading Pour Concrete Pad Pad NOT connected to house Lot **Bottom Drains** 18x36 Tapered **Electric Heat Pump** 6' Depth (per PI **Undertrack Cover** Homeowner to remove treed prior to install - remove stumps In-wall Ladder Homeowner to remove 2 sections of 22'3" 20' D.& U.E. fence prior to installation Access on left side of house 100.00' Adjoiner's Fence ± HAHN SURVEYING GROUP, INC. CERTIFIED: 04/22/2020 Land Surveyors 8925 N. Meridian Street, Suite 120